



Note by Jeremy Appt March 12, 2012
 Photos suggest there is a gap between the rock and inside of the valve house.
 See attached Photos