




SITE ASSESSMENT SURVEY

January 2009

UNIFORM POLICE DISTRICT HEADQUARTERS, MAYDAN SHAHR DISTRICT MAYDAN WARDAK PROVINCE – AFGHANISTAN

This site assessment survey is based on a 15000 square meter master plan specified for UP-District #2 -HQ in the Maydan Shahr capital of Maydan Wardak province, 30 km south of Kabul city.

LOCATION MAP – Figure 1





MINISTRY OF INTERIOR



This site is held solely by Government of Afghanistan authorities where bounded by Northern by a wadi, South and western by Municipality ownership and eastern mountain.

AERIAL SITE PHOTO – Figure 2





TABLE OF CONTENTS

Part A: Project Details	PAGE
Project Assessment Survey	4
TABLES	
TABLE A-1 Site Corner Grids	4
Part B: Attachments	
TABLES	
TABLE A-1 Site Corner Grids	4
APPENDICES	
APPENDIX A: Site Sketch with GPS Details	19
APPENDIX B: Site Specific GoA Documents	20
APPENDIX C: Field Reports (Dari and English)	28
APPENDIX D: Additional Site Photos	37
APPENDIX E: UP District Maydan Shahr Master Plan	38





MINISTRY OF INTERIOR



PART A: PROJECT DETAILS

PROJECT ASSESSMENT SURVEY

DATE OF ASSESSMENT: [17 DEC 2008](#)

NAMES OF ENGINEERS: [MOI rep. SAID WAKIL](#)
[MACTEC rep. MOHD. YOUSEF](#)

SITE GENERAL CONDITIONS

CONDITIONS OF PROPOSED SITE:

Land is owned by the Afghan Government and there are not any private claims nor disputed ownership claims. The site is located 2km south east of Maydan Wardak Provincial Capital named Maydan Shahr. Currently, the site is an unimproved desert. Land use based on Municipality Mastered plan: northern a great deal of erosion caused during the rainy season, South and western by Municipality ownership and eastern mountain risen Site may be extended towards east and south and west.


TABLE A-1: SITE CORNER GRIDS

Site Description	Site Location	Points	Easting	Northing	Elevation
UP District HQ	Maydan Shahr	1	68° 52' 00.8"	34° 22' 29.7"	2,278 meters
		2	68° 52' 3.6"	34° 22' 31.8"	2,274
		3	68° 51' 59.7"	34° 22' 35.5"	2,257
		4	68° 51' 56.7"	34° 22' 33.3"	2,251





SITE WITH GRID POINTS – Figure 3





SITE CORNER LOCATIONS (GPS Coordinates)

Corner #1 E: 68° 52' 00.8" N: 34° 22' 29.7"



Photo 1-1 View to East





Photo 1-2 View to North



Photo 1-3 View to Northwest





Photo 1-4 View to Northwest



Photo 1-5 View to West





MINISTRY OF INTERIOR



Corner #2: E 68° 52' 3.6" N 34° 22' 31.8"



Photo 2-1 View to South



Photo 2-2 View to West





Photo 2-3 View to Southwest



Photo 2-4 View to Northeast

Corner #3 E 68° 51' 59.7" N 34° 22' 35.5"





Photo 3-1 View to East



Photo 3-2 View to South





Photo 3-3 View to Southeast



Photo 3-4 View to Southeast

Corner #4 E 68° 51' 56.7" N 34° 22' 33.3"





Photo 4-1 View to North



Photo 4-2 View to East





Photo 4-3 View to Northeast



Photo 4-4 View to Northeast

SITE EXISTING FACILITIES None.


SITE DEBRIS OR SIGNIFICANT TRASH None.





LAND USE OF SURROUNDING AREA – Figure 4

The site may be expanded in each direction.



SITE UTILITIES

A. ELECTRICITY

There is no electricity available in proximity to the site.

B. WATER

The water table is about 120m below the surface, reported by women affair center where bored a tube well inside which is near by the area.

C. SEWAGE





There is no existing sewage or water treatment system. Slope of terrain is from west to east.

SITE CONSTRUCTABILITY

VEHICLE ACCESS

The site is 2 km from the asphalted Main Kandahar-Kabul road that passes through the capital Maydan Shahr. The main road in the area is ordinary road where there are seasonal problems in winter.

SITE TOPOGRAPHY

- A. HILLS (GRIDS) None.
- B. DEPRESSIONS (GRIDS) None.
- C. WADIS (GRIDS)

During the rainy season, floods from the mountains to the east pass quickly in two small wadis at the site.

D. DRAINAGE ISSUES/FLOOD CONTROL

There is no alternate drainage available. The area slopes from west to east.

E. SITE ISOLATION

During precipitation, water runoff at adjusted wadi will affection need for isolation

F. MINES & DEMINING

Local police report that area is clear of mines and unexploded ordinance.

G. ADDITIONAL CONDITIONS

The area of the site located in the wadi is extra cold in winter due to winds.

SITE RESOURCES:

ROAD ACCESS: ordinary access road connects to Kabul Kandahar Main road 2km away.

CONSTRUCTION MATERIALS:

LABOR: Skilled labor (daily: \$12-17) and unskilled labor (\$5-8) available at nearby market.

TELEPHONE: Telecommunication is available using Roshan, Etisalat, and Beseem networks.

ELECTRICITY: Not available.

PUBLIC TRANSPORTATION: Not available, though, for-hire passenger vehicles available in Maydan Shahr.





HEALTH CLINIC: There is a clinic located at Maydan Shahr (2 km).

FUELS: Standard fuel pumps are available (\$1.30/litre petrol) at 2 km.

LAND OWNERSHIP: Site belongs to the Ministry of Interior.

SECURITY: Situation is at the moment stable, but the area requests more police attention.

MINES: The area is clear of mines.

OTHER INFORMATION:


SITE ELEVATION: 2,257 meters above sea level

TYPE OF SOIL: Type 2

WATER TABLE LEVEL: Not recorded; but, reportedly, nearby wells 120 meters deep

FREEZING POINT LEVEL: 0.8 m deep

SITE RESOURCES – Figure 5





PART B: ATTACHMENTS

LOCATION OF DISTRICT IN MAYDAN WARDAK PROVINCE – Figure 6






MINISTRY OF INTERIOR



APPENDIX A: SITE SKETCH WITH GPS DETAILS





APPENDIX B: SITE SPECIFIC OFFICIAL GoA DOCUMENTS

نظریه هیات موظف

شناسنامه موضوع

ساحه مورد نظر: تعمیر ماموریت سمت

مساحت: هفت ونیم جریب زمین

حدود اربعه:

۵- شمالا: شیله

۶- جنوبا: زمین های ریزرفی شاروالی

۷- غربا: ساحه ریزرفی شاروالی

۸- شرقا: کوه عام

موقعیت: مرکز میدان شهر

۱۷.۹.۱۴
مقام محترم ولایت

به اساس فیصله شورای اداری مورخ ۱۳۸۷/۹/۱۱ مقام محترم ولایت میان اعضای هیات نظر خویش را احترامانه چنین ابراز می داریم:

- ۱- ساحه مورد نظر برای تعمیر ماموریت سمت پولیس واقع در مرکز میدان شهر مطابق حدودات اربعه و مساحت که در شناسنامه موضوع فوقادرج گردیده است تثبیت گردید.
- ۲- ساحه تثبیت شده کاملاً دولتی بوده و از جمله ساحه بایر و شامل مواد ۱۴ و ۱۶ فرمان شماره ۸۳ مقام محترم ریاست دولت انتقالی اسلامی افغانستان و نیز شامل ماده ۴۸۲ قانونی مدنی میباشد.
- ۳- ساحه مورد نظر و تثبیت شده در کروی جداگانه به امضای اعضای هیات رسیده که تواما با این نظریه به مقام محترم ولایت جهت ملاحظه تقدیم می گرد.

بالحترام

امضای اعضای هیات

امضای اعضای هیات

EXHIBIT ONE





MINISTRY OF INTERIOR



Opinion of Missions

Identity of Issue

Checked the issue
Deputy for Provincial governor
Signature
1387/9/13

Proposed area: Building of Urban district Police Station
Area: 7.5 Jerieb

Four Directions (Land use):

- 5- Northern: Canyon (wadi)
- 6 - Southern: Municipality Properties
- 7 - Western: Municipality Properties
- 8 - Eastern: Mountains

Location: Center of Maidan Shahr

.....
According to decision of Administration Council, of Provincial Governor Office, dated 1387/9/11, the Mission team expresses their contained information and ideas as such:

- 1- The area which has been selected for Urban District Police Station, located in the center of Maidan Shahr and it's determined according to above four directions (Land use) and area.
- 2- The area belongs to government, and uncultivated areas have been recorded in the article No.14 /16, of order No. 83 of President of Islamic republic of Afghanistan and also contained in material No. 482 of civil law.
- 3- The area has been signed by team of Mission and submitted to Provincial Governor Office for consideration.

Truly Yours
Signature of member

EXHIBIT ONE TRANSLATED





MINISTRY OF INTERIOR




EXHIBIT TWO





MINISTRY OF INTERIOR




EXHIBIT TWO TRANSLATED





١٣٨٧/٩/٤



١٣٥
٤٩

وزارت امور داخله
قوماندانی امنیه میدان وردگ
مدیریت ع اداری و تاميناتى
مدیریت لوژستیک
آمریت تعمیرات

به مقام محترم ریاست تسهیلات وزارت امور داخله!

بجواب مکتوب (3541) مورخ 1387/8/18 آمریت دفتر شما احترامانه تحریر میگردد.
درباره پروژه پولیس حوزه امنیتی در میدان شهر و پروژه پولیس قوماندانی امنیه میدان وردگ
موضوع به مقام محترم ولایت پیشنهاد و در مجلس اداری تصویب به عمل آمد که درباره نماینده
قوماندانی امنیه و نماینده قضایای دولت و نماینده مدیریت زراعت و نماینده شاروالی ولایت درباره
توظیف از صورت اجراءات خویش اطمینان دهند که هیئت موظف موازی هفت و نیم 7.5 جریب
زمین را به خاطر پروژه پولیس حوزه امنیتی و موازی 34 جریب زمین را بخاطر پروژه پولیس
قوماندانی امنیه میدان وردگ در ولایت میدان وردگ سروی مکمل و نشانی نمودند که اینک وسیله
هذا دونقل نظریه هیئت موظف و دونقل فوتوکاپی نقشه و اسکچ ساحه متذکره غرض اجراءات بعدی
به مقام محترم گسیل درباره چطوریکه هدایت می فرمایند قابل تعمیل است.

با احترام
مل پاسوال عبدالیمین مظفرالدین
قوماندان امنیه میدان وردگ

EXHIBIT THREE





MINISTRY OF INTERIOR



**Ministry of Interior & Affairs
Security Command of Maydan Wardak Province
General Directorate of Administrative & Security
Logistic Department
Construction Department**

Dated (1387/9/30)

Dated (125/69)

To facility department of Ministry of Interior!

Answer of letter No (3541) Dated (1387/8/18) your respected office is writing as follow:
On the subject of project for district Police headquarter in Maydan sharhar and provincial Police headquarter in Maydan Wardak , issue suggested and approved in provincial administrative assembly, representative of Security uniform of police, Representative of Government Judicial, Representative of Directorate of Agriculture and Representative of Municipality to sure them about this issue.

The Mission team figure out in the survey about (7.5) Jerieb land for the project of Police security command and around (34) Jerieb land for Police project of security command of Miadan Wardak in Maydan Wardak Province.

Additionally, two copy of maps and sketch of area sent to the gestle for farther doing through delegation, they are advising us we will do it like that.

**Sincerely
Abdul Yameen “Muzafaruldin”
Security command of Maydan Wardak Province**

EXHIBIT THREE TRANSLATED





MINISTRY OF INTERIOR



قرمان نژادی افسانه میزبان وردک

بیت اولاد و نام میزبان

دفتر

۲۸۸
۶۱۱

۸۷/۱۹/۱۰

بیت حرم کورسید

مکتوبه شماره ۹۳۸ امرت در مقام فرمان نژادی افسانه و اصله و نقل کتبه ثبت
۸۷/۱۹/۱۰

مکتوبه شماره ۲۴۸۷ امرت بناد و اولاد طر ولایت میزبان وردک و اولاد و میزبان وردک
۸۷/۱۹/۱۹

مکتوبه شماره ۲۵۲۱۴ امرت در مقام سرپرست اولاد افسانه میزبان وردک
۸۷/۱۸/۱۸

اداره نام میزبان مقام حرم وزارت امور در اولاد شرح زیره رسید به امرت

وزارت امور در اولاد در نظر دارد تا بهرری ۲۸ پروژه بر اولاد زمین ثبت نماید

در این باره انقدر سرکل طر نامیده اولاد سرپرست وزارت در اولاد مقام

نامیده اولاد مارکو بر اولاد قرار داری و مکتوبه افسانه میزبان وردک کتبه شماره ۱۸۱۸

تا بهرری ۲۸ پروژه در اولاد

۱- پروژه بر اولاد حوزو افسانه در میزبان وردک ولایت میزبان وردک

۲- پروژه بر اولاد فرمان نژادی افسانه میزبان وردک در میزبان وردک افسانه میزبان وردک

بهین دلیل مکتوبه افسانه میزبان وردک تا بهرری ۲۰ حوزو زمین همراه اولاد

سرکل همکاره لازم نماید تا بهرری سرکل کتبه شماره ۱۸۱۸ مکتوبه در اولاد

تعمیر شده در دسترس افسانه میزبان وردک باشد

مراتب اولاد نقد بر اولاد و بهرری سرکل افسانه میزبان وردک تا بهرری اقدام بر اولاد

تا بهرری اقدام در اولاد دهد

مراتب اولاد نقد بر اولاد افسانه میزبان وردک تا بهرری اقدام بر اولاد همکاره همراه اولاد

نموده تا بهرری اقدام تا بهرری اولاد لازم نموده بهرری اولاد بر اولاد افسانه میزبان وردک

اولاد دهد

مراتب اولاد فوق نقد بر اولاد افسانه میزبان وردک تا بهرری اقدام بر اولاد

بیت حرم کورسید همکاره همراه اولاد نماید

پاکستان

اداره نام میزبان

EXHIBIT FOUR

Security Command of Maydan Wardak





MINISTRY OF INTERIOR



Administrative & Security Directorate Office

No (688/611)

Dated (1387/9/10)

To respected Logistic department!

Through Letter No (948) Dated (1387/9/10) director of Security command is received and writing as such:

Letter No (2487) Dated (1387/9/9) Directorate of Documents and relation is received and writing as such:

Letter No (3541) Dated (1387/8/18) Facility department, Logistic department, deputy of security & Administrative of Ministry of Interior are received with following details:

Ministry of Interior considered to fix the land for (38) Police project, for this issue Engineer Sayed Gul khan Representative of facility department of Interior Ministry, Representative of Marcopolo (Contractor) and MACTEC (The Facilitator Company) are introduced to you that they fix the land for the projects of:

- 1) Police project of district security command of Maydan Shahr in Maydan Wardak
- 2) Police project of provincial security command of Maydan Shahr in Maydan Wardak

There for the issue is recognized you for full coordination that they can fixe the land (20) Jerieb with survey group, that survey group can be able to get the information on time.

The above progress steps in mention and the Survey team are introduced to you, hope that you have understanding with the Municipality.

The cases are mention to you, representative of facility department would have coordination to each other, the implementation will be done by the Municipality and you have to sure the provincial governor about it.

You understand the issue, see the text of letter and corporate each other with the facility department.

Sincerely
Wafa “Zeyaye”
Admin Manager

EXHIBIT FOUR TRANSLATED

APPENDIX C: FIELD REPORTS (DARI & ENGLISH)





MINISTRY OF INTERIOR



د ملي پوليس د ساحاتو تشخيصول
دا فورمه بايد مخکه له تگ څخه ډکه شي.

امنيتي وضع: بڼه نورمال خراب
لید: 2257m په متر
سوالونه د ځمکي د مالکیت په اړه:

د ساحي نوم: هوزه امنيتي 2 ميدان وردگ
د ځمکي د تشخيصولو نېټه: 17-12-2008
د انجنير نوم: _____

محمد دوستي
دغه ساحه له ولايت څخه 2257m

د ساحي عمومي وضع

د ځمکي د اوسني پوښنهادي حالت:

دغه ساحه يوه نمرن کسبه ده چې د ميدان وردگ ولايت جنوب شرق لورون ته په 2257m (دوه کيلومتره) کې پروت ده. دغه ساحه له جنوب نه شرق لورون ته زيات ميل لرونه مگر د سيلاب اوبو د ساحي جنوب او شمال لورون ته هم رودون دي. ځير ييزه بڼه د بېلابېلو اندازه د باران اوبو لاندې ساتي تر اوسه د شرق، جنوب او شمال لورون ته هم رودون دي او جنوب او شمال لورون ته هم د سيلاب رودون دي او تر ب لورون ته هم رودون لري. دغه ساحه په ماشين پلدين موجوده د تثبيت شوي ځمکي د نوشونو موقعيت د کور دینات (جي پي اس) په حساب

نوټ 1# $N: 34^{\circ} 22' 29.7''$; $E: 068^{\circ} 52' 00.8''$
نوټ 2# $N: 34^{\circ} 22' 31.8''$; $E: 068^{\circ} 52' 03.6''$
نوټ 3# $N: 34^{\circ} 22' 35.7''$; $E: 068^{\circ} 51' 59.7''$
نوټ 4# $N: 34^{\circ} 22' 33.3''$; $E: 068^{\circ} 51' 56.7''$

د ساحي موجوده تسهيلاتو حالت

د تثبيت شوي ساختمان د نوشونو موقعيت کور دینات (جي پي اس)

کور دینات (جي پي اس) د ساختمان 1#
نوټ 1# اخيستل شوي تصوير
نوټ 2# اخيستل شوي تصوير
نوټ 3# اخيستل شوي تصوير
نوټ 4# اخيستل شوي تصوير



MINISTRY OF INTERIOR



د ملي پوليس د ساحاتو تشخيصول
دا فورمه بايد مخکه له تگ څخه ډکه شي .

ساختمان 2# کوردينات (جی پی اس)

په ساحاتو کې تعبير موجود نه دی .

نوش 2# اخيستل شوي تصوير

نوش 1# اخيستل شوي تصوير

نوش 4# اخيستل شوي تصوير

نوش 3# اخيستل شوي تصوير

ساختمان 3# کوردينات (جی پی اس)

نوش 2# اخيستل شوي تصوير

نوش 1# اخيستل شوي تصوير

نوش 4# اخيستل شوي تصوير

نوش 3# اخيستل شوي تصوير

ده ساختمان اندازه او ده منازلو تعدادونه

ساختمان 1#

ساختمان 2#

ساختمان 2#

ساختمان 3#

ساختمان 3#

ساختمان 3#

د ساختمان ډولونه

ساختمان 1# (مواد , د ساختماني شيوه او عمومي اوضاع) تعبير موجود نه دی .





MINISTRY OF INTERIOR



د ملي پوليس د ساحاتو تشخيصول
دا فورمه بايد مخکه له تک څخه ډکه شي .

په ساحي کې فصله قصير وچود نه لري .

ساختمان#2 (مواد , د ساختماني شيوه او عمومي اوضاع)

وچود نه لري

ساختمان#3 (مواد , د ساختماني شيوه او عمومي اوضاع)

وچود نه لري

د کار ليوونکي مواد او کثافات د ساحي

کشفه په ساحي کې وچود نه لري .

ځمکي د ساحي په اطرافوکي ټول اوجنوب او شرق لور ته کې د سېکېټ لورونو او وچود نه لري .

وچود نه لري . کله چې جنوبي او شرقی طرف ته لورونو او وچود نه لري ، نو په ساحي کې وچود نه لري .
آيا ساحه د پراختيا وړتيا لري که نه؟ په کوم لوري ځمکه وجود لري؟

شرق ، کله چې اوجنوب لور ته د پراختيا وړتيا لري .





MINISTRY OF INTERIOR



د ملي پوليس د ساحاتو تشخيصول
دا فورمه بايد مخکۀ له تک څخه ډکه شي .

عام المنفعة تسهيلات

A. د برق سيستم

ښاري برېښنا په کومه کچه او ظرفيت او فرکانسي د ښاري څانگه

تعمیر ښار برېښنا سره .

B. آوبه د اوبه سطح به متر 120cm

استوگن کسان له څه ډول اوبو څخه استفاده کوي؟

د ځاه نه اوبو څخه استفاده کوي

C. د فاضلابو سيستم

د فاضلابو سيستم قبلي موجود نه وي بيا به د سره جوړېږي .

د ساحه ساختمان

(لاسرسی نقلیه وسایطو او سرک ته) قيريزی □ خامه □ خراب □ او يا د ترميم لاندی □

څه ډول ستونزي د ژمي په موسم کې وجود لري

که چيرته موسم باران وښکي وقت ولاړه نه شي کولای .

توپوگرافي

مهرباني وکړي مهم تغيرات په نما کې وښيي

(A) د محلي ټپو کور دینات





MINISTRY OF INTERIOR



د ملي پوليس د ساحاتو تشخيصول
دا فورمه بايد مخکۀ له تگ څخه ډکه شي .

(B) د خندقونو کورډينات
N: 34° 22' 33,6" 22 60 ۰ E: 68° 51' 59,9"

مخکۀ له تگ څخه ډکه شي .

(C) د وادي کورډينات
له تصوير سره

(D) د سيلاب د راتلو او کنترول لاره

د سيلاب د راتلو لاره بايد استازي راپور ورکړي .

(E) د ساحه ايزوليشن

کوم څه ننوتل او ليدل شوي دي .

کومه ساحه چه سيندونو او غرونو ته د نژده د ايا دغه ساحه په نومور و احاطه شويده؟

(F) د ساحه د پاکولو په باره معلومات

د مينونو د پاکولو په باره معلومات

کوم څه تېر شوي دي .

پاک شوي دي .

نور معلومات چي په ساختمان باره باندې اغيزه لري؟

که صدمه تېره شويده او اوس اوس

نور معلومات چي په ساختمان باره باندې اغيزه لري .





MINISTRY OF INTERIOR



د ملي پوليس د ساحاتو تشخيصول
دا فورمه بايد مخکۀ له تګ څخه ډکه شي .

که سيټيز زيات لرګي تر لقيدورت زيات اغيزه من
کوي .

د محلي منابع :

- کم تجربه کارمندان د زيات اوږد راتګ سپارښت
- باتجربه کارمندان د زيات سپارښت په ساحه
- د ساختماني مواد لکه شګه , چغل و دبره په ساحه کې موجوديت لري موجوديت نه لري. 25-30 km
- نور مواد لکه سمنت , گول سيخه, خښته , گچ , سريش له کابل او ١٥٦ -
- تزرورسيونر څخه راوړل شي
- ده مخابراتي سيستم موجوديت لري موجوديت نه لري.
- د سوند توکي لکه لرګي , بنزين ډيزل ضرورت لپاره موجوديت لري موجوديت نه لري.
- عامه ترانسپورت لکه ملي بس , نکسي , مسافر پرونکي بس , موجوديت لري موجوديت نه لري
- ساختماني ماشينري او وسايل په له کابل څخه راوړل شي
- د سوند توکي ماشينري لپاره موجوديت لري موجوديت نه لري
- کلنيک په ساحه کې موجوديت لري موجوديت نه لري
- اونور:

مهرباني وکړي د ترسيم شوي ساحوي پلان علاوه کړي





Utilities

A. Electricity

Quantity available from the City Grid & Dependability/Frequency of City Power
No at proposed land and nor capital have Electricity. surrounding people use for lighting private generators

B. Water

Water Table in Meters: 120m

Near to the area inside Women affair office is 120 deep bored well, at the same time at the west of the area is Karizz from which small amount of water comes out and use for agricultural purposes.

How do local inhabitants get water?

Surrounding local people use karizz water for there daily uses. And the nearest women affair office uses 120m deep tube well.

C. Sewage

No exist system.

Constructability of the Site

Vehicle access (condition of roads) Asphalt Gravel Bad Under repair

To the area is ordinary road.

What problems in winter season or rainy season?

The road is un-gravel so at winter season has little transportation problems.

Topography

Please Note Significant changes in elevation

A. Hills (Grids)

No hills

B. Depressions (Grids)

One small cubic meter pit is at the middle of the area.

Ele.2260m, N: 34° 22'33, 6", E: 68° 51'59, 9", Photos Taken attached

C. Wadis (Grids)

Washouts Photos Taken attached

No





MINISTRY OF INTERIOR



D. Drainage Issues/ Flood Control

No. to keep in mind for the future planning slope is east to west.

E. Site Isolation.

To the North of Land is a wadi will have affection on site need to provide isolation and two small wadis passes rain water through area at two sides of the area, will have also future affection on site, suggested to isolate the area.

Is Site isolated because of nearby river, creek, or mountains?

No.

F. Mines & Demining

Based on local and police information no Mines at site.

Any additional conditions affecting the Site's Constructability

No

LOCAL or NEARBY RESOURCES:


- Unskilled labors will be mobilized from – Yes: Local, Wedge \$5-8/day.
- Skilled labors will be mobilized from. Yes: Kabul market. Wedge \$12-17/day.
- Material like Sand, Gravel, Stone, Crush, Not Available ✓ Available (from surrounding area distance 0-5km).
Bricks 25-50 km Shakar Dara or Deh Sabz district.
- Other material like Cement, Steel bar, Lime, Gypsum will be mobilized from : Kabul city 30km
- Telephone communication Not Available Available at site ✓
- Fuel For heating and cooking Not Available ✓ Available (wood , diesel) (2 km distance)
- Public Transportation Not Available Scarce ✓ Available (Buses, Taxis, Coaches)
- Construction Machinery and Equipment will be mobilized from _Kabul.
- Fuel For machines Not Available ✓ Available (2km distance)
- Clinic Not Available ✓ Available at site (at 1 km distance)
- Other:

Attached Hand Drawn Site Plan.





MINISTRY OF INTERIOR





APPENDIX D: ADDITIONAL PHOTOS



Drainage channel is located within limits of site assessment




Rock pile is located within limits of site assessment





APPENDIX E: UP DISTRICT MAYDAN SHAHR MASTER PLAN



SCALE	AS SHOWN
PROJECT	AFGHAN NATIONAL SECURITY FORCE Comprehensive Plan for Facility Development
CLIENT	UP District HQ (60p) Maydan Wardak
DOCUMENT	Master Site Plan
DESIGNER	MACTEC ARCHITECTURAL & ENGINEERING CONSULTANTS 1000 1st Street, Suite 100 Ft. Collins, CO 80501 Tel: 970.221.1111 Fax: 970.221.1112
APPROVED BY	
DATE	09/27/2010
BY	3/10/10
FOR OFFICIAL USE ONLY	





MINISTRY OF INTERIOR



THIS PAGE INTENTIONALLY LEFT BLANK.

