

SITE ASSESSMENT SURVEY

UNIFORM POLICE, DISTRICT HEADQUARTERS, AFGHANISTAN
STABILIZATION PROGRAM (ASP) ZIROK DISTRICT, PAKTIKA
PROVINCE

CONTRACT #: W5J9JE-10-A-0010

PROJECT #: PDHE031901DH

September.25.2010

Submitted to the:

US Army Corps of Engineers

Afghanistan Engineer District

Prepared by:

INTELLIGENT EYES CONSTRUCTION COMPANY

Survey and Design Team

Submittal Date: 25.September.2010



Customer is our King
Quality is our Wing

SITE ASSESSMENT SURVEY

UNIFORM POLICE, DISTRICT HEADQUARTERS, AFGHANISTAN
STABILIZATION PROGRAM (ASP) ZIROK DISTRICT, PAKTIKA
PROVINCE

CONTRACT #: W5J9JE-10-A-0010

PROJECT #: PDHE031901DH

September.25.2010



Intelligent Eye Construction Company

Tel: (93) 799-053-901 / (93) 799-712-725 / (+93) 788-50-7006

Email: iecc@live.com




FIGURE 1 GOOGLE MAP





Customer is our King
Quality is our Wing



Intelligent Eye Construction Company
Tel: (93) 799-053-901 / (93) 799-712-725 / (+93) 788-50-7006
Email: iecc@live.com



Customer is our King
Quality is our Wing




Intelligent Eye Construction Company
Tel: (93) 799-053-901 / (93) 799-712-725 / (+93) 788-50-7006
Email: iecc@live.com



Customer is our King
Quality is our Wing


FIGURE 3 EXISTING SITE PLAN





Customer is our King
Quality is our Wing

FIGURE 4 SITE PICTURES PLAN





2. SITE PHOTOGRAPHS



P1: This picture is taken from southwest side shown northeast side of project site, boundary wall around the site and US Army comp near to the project site.

P2: This picture is taken from east side shown west side of project site.



Customer is our King
Quality is our Wing



P3

P4



P3: This picture is taken from northwest side shown southeast side of project site, boundary wall around the site and guest house in the project site.

P4: This picture is taken from south side shown north side of project site; mosque and weapon storage in the project site.



P6



P5: This picture is taken from west side shown east side of project site, boundary wall around the site and uncompleted UP DHQ building in the project site.

P6: This picture is taken from southeast side shown northwest side outside the project site and boundary wall around the project site.




P7: This picture is taken from southeast side shown northwest side of project site, boundary wall around the site and guest house in the project site.

P8: This picture is taken from southwest side shown northeast side of project site; boundary wall around the project site and uncompleted UP DHQ building in the project site.



Customer is our King
Quality is our Wing



P9: This picture is taken from southwest side shown northeast side of outside the project site; boundary wall around the site and Guard Tower in the project site.

P10: This picture is taken from west side shown east side; road to the UP DHQ building and US Army comp guard tower near to the project site.



Customer is our King
Quality is our Wing



P11

P12



P11: This picture is taken from east side shown west side of project site, guest house and mosque in the project site.

P12: This picture is taken from northwest side shown southeast side of project site and main gate of the project site.



Customer is our King
Quality is our Wing



P13

P14



P13: This picture is taken from northeast side shown southwest side of project site and guest house in the project site.

P14: This picture is taken from southwest side shown northeast side of project site; boundary wall around the project site and uncompleted UP DHQ building in the project site.



Customer is our King
Quality is our Wing



P15: This picture is taken from northeast side shown southwest side of project site, boundary wall around the site and uncompleted UP DHQ building in the project site.

P16: This picture is taken from northeast side shown southwest side of project site; boundary wall around the site and Guard Tower in the project site.



Customer is our King
Quality is our Wing



P18



P17: This picture is taken from northwest side shown southeast side, outside of project site, and BHC clinic near to the project site.

P18: This picture is taken from southeast side shown northwest side; boundary wall around the site, uncompleted UP DHQ building in the project site and US Army comp near to the project site.



Customer is our King
Quality is our Wing



P20



P19: This picture is taken from east side shown west side of project site and mosque in the project site.

P20: This picture is taken from north side shown south side of project site and mud wall building which uses as jail in the project site.



P21: This picture is taken from north side shown south side of project site, mud wall jail building and guest house in the project site.

P22: This picture is taken from northeast side shown southwest side of project site; boundary wall around the site and weapon storage in the project site.



P24



P23: This picture is taken from northeast side shown southwest side; boundary wall around the site and governmental land near to the project site.

P24: This picture is taken from northwest side shown southwest side and boundary wall around the project site.

SITE ASSESSMENT CHECKLIST

To be completed before leaving the site.

Name of Site : **Zirok UP DHQ**

Date of Assessment : **28/August/2010**



Customer is our King
Quality is our Wing

Points	Northing	Easting	Elevations
Corner #1	33.15671 ^o	69.30659 ^o	2357 m
Corner #2	33.15731 ^o	69.30693 ^o	2359 m
Corner #3	33.15707 ^o	69.30741 ^o	2360 m
Corner #4	33.15647 ^o	69.30707 ^o	2358 m

Center Coordinate and Elevation:

Center	33.15683 ^o	69.30702 ^o	2354 m
--------	-----------------------	-----------------------	--------

Bench Mark Coordinate and Elevation:

Bench Mark	33.15671 ^o	69.30659 ^o	2357 m
------------	-----------------------	-----------------------	--------

EXISTING FACILITIES ON SITE

There is uncompleted building for UP DHQ, Mosque, Hesco wall Weapon storage, toilets and some other old building in the project site. The UP DHQ commander currently uses the guest house as office which is located in the project site. This site is surrounded by stone wall. There are no known claims or disputes about land ownership.